

Pictures of 1416 9th St. NW
Taken on January 6th, 2007




Front view from 9th Street.

Close up of front door.
Interior is filled with trash
and debris and interior is
open to the elements, a
violation of the vacant
property maintenance
standard.



Pictures of 1416 9th St. NW
Taken on January 6th, 2007



Rear of building.



Unsecured rear window.

